


Vehicle Safety Inspection Report

Stock 48
 VIN6 5094415
 Mileage 14195
 # Of Keys 2
 Exterior Inspected by:
Angel Ruiz

Mark any damage found on the vehicle exterior with "X"



shutterstock.com · 309121715

Hood Components

- Hood Release
- Hood Prop

Wipers Components

- Fluid Level
- Operation
- Coolant Level

Braking System

- Parking Brake
- Brake Fluid
- Calipers
- Drums
- _8_LF _8_RF _8_LR _8_RR

Seating Areas

- Adjustments
- Door Latches/Buttons
- Safety Belts Operation
- Headrests
- Carpet Condition
- Seat Fabric Condition
- Floor Mat Condition
- Door Trim Panel Condition
- Fold Down Latches
- Integrated Child Safety Seats
- Headliner Condition

Suspension Components

- Shock Absorbers
- Struts
- Suspension Bushings
- CV Boots Axles
- Stabilizer Bars

Battery Health Check

- Charger Included
- Port Damage
- Batt Health Check
- Charging

Luggage Department

- Luggage Compartment
- Weather Stripping
- Luggage Compartment Trim
- Lighting

Audio System

- Radio/Bluetooth
- Speakers
- Car Play

Instrumentation/Controls

- Instrument Panel Gauges
- Horn
- Window Controls
- Mirror Controls
- Door Lock Controls
- Steering Wheel Controls
- Glove Box Hatch
- A/C Condition
- Rear Window Defroster
- Sun Visors
- Moon Roof
- Courtesy Lights
- Heater Condition
- Remote Trunk Release

Lights & Lenses

- Headlamps High/Low with Aim
- Parking Lamps
- Reverse Lamps
- Hazard Lamps
- Turn Signals
- Running Lights
- License Plate Illumination
- Interior Dome Lights
- Fog Lamps

Tires & Wheels

- Spare Tire Condition
- Tire Pressure
- Wheels General Condition
- Wheel Covers
- Tread Depth
- _4_LF _3_RF _4_LR _4_RR

Glass

- Windshield
- Side Window Driver
- Side Window Passenger
- Rear Side Windows
- Pillar Camera Glass
- Rear Window/Hatch
- Moon Roof

Technician Team Member Inspected:
 Date:

Angel Ruiz
03/09/2026

Additional Comments: 4 new tires