



805 SW 10th St.
 Renton, WA 98057
 (425) 217-2277
 www.ecoautonw.com

Customer: 10281 **Stock #:** **VIN: 5YJ3E1EA2JF102926** **2018 Tesla Model 3 RWD**

Op	Acct	Status	Op Code	
A	SCP	Posted	MISC	Customer Pay

- Tesla Charge Port Door Repair
- REPLACED CHARGE PORT DOOR. AFTER REPLACEMENT CHARGE PORT DOOR IS OPERATING PROPERLY

Labor	Tech	Hours	Sale				
	1005	0.50	105.00				
Parts	QTY	Part #	Description	Price	Core Chg	Core Crd	Sale
	1	NPN-1084854-00-F	CHARGE PORT DOOR - TOP ASSEMBLY - GEN3 - NA	200.79	0.00	0.00	200.79
Totals:	Labor: 105.00		Parts: 200.79				305.79

Other	Description	
	State Sales Tax & City Sales Ta	32.11
	Shop Supplies & Technology F	10.00

Labor: 105.00 Parts: 200.79 Sublet: 0.00 Taxes: 32.11 Charges: 10.00 Discounts: 0.00 Total: 347.90

Customer Pay Total 347.90

Payments	Payment Date	
Mastercard	03/13/2026	-347.90
	Amount Due	0.00

RO Total 347.90

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	200.79				200.79
Labor	105.00				105.00
Deductible	0.00	0.00	0.00		
Taxes	32.11	0.00	0.00	0.00	32.11
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	10.00	0.00	0.00	0.00	10.00
Payer Total	347.90	0.00	0.00		347.90