


Vehicle Safety Inspection Report

Stock _____
 VIN6 5101294
 Mileage 40689
 # Of Keys 1
 Exterior Inspected by:
Angel Ruiz

Mark any damage found on the vehicle exterior with "X"



shutterstock.com · 309121715

- Hood Components**
- Hood Release
 - Hood Prop
- Wipers Components**
- Fluid Level
 - Operation
 - Coolant Level

- Braking System**
- Parking Brake
 - Brake Fluid
 - Calipers
 - Drums
 - _8_LF _8_RF _8_LR _8_RR

- Seating Areas**
- Adjustments
 - Door Latches/Buttons
 - Safety Belts Operation
 - Headrests
 - Carpet Condition
 - Seat Fabric Condition
 - Floor Mat Condition
 - Door Trim Panel Condition
 - Fold Down Latches
 - Integrated Child Safety Seats
 - Headliner Condition

- Suspension Components**
- Shock Absorbers
 - Struts
 - Suspension Bushings
 - CV Boots Axles
 - Stabilizer Bars

- Battery Health Check**
- Charger Included
 - Port Damage
 - Batt Health Check
 - Charging

- Luggage Department**
- Luggage Compartment
 - Weather Stripping
 - Luggage Compartment Trim
 - Lighting

- Audio System**
- Radio/Bluetooth
 - Speakers
 - Car Play

- Instrumentation/Controls**
- Instrument Panel Gauges
 - Horn
 - Window Controls
 - Mirror Controls
 - Door Lock Controls
 - Steering Wheel Controls
 - Glove Box Hatch
 - A/C Condition
 - Rear Window Defroster
 - Sun Visors
 - Moon Roof
 - Courtesy Lights
 - Heater Condition
 - Remote Trunk Release

- Lights & Lenses**
- Headlamps High/Low with Aim
 - Parking Lamps
 - Reverse Lamps
 - Hazard Lamps
 - Turn Signals
 - Running Lights
 - License Plate Illumination
 - Interior Dome Lights
 - Fog Lamps

- Tires & Wheels**
- Spare Tire Condition
 - Tire Pressure
 - Wheels General Condition
 - Wheel Covers
 - Tread Depth
 - _7_LF _5_RF _4_LR _7_RR

- Glass**
- Windshield
 - Side Window Driver
 - Side Window Passenger
 - Rear Side Windows
 - Pillar Camera Glass
 - Rear Window/Hatch
 - Moon Roof

Technician Team Member Inspected:
 Date:

Angel Ruiz
02/19/2026

Additional Comments: Rear left tire is at 4/32nds recommending replacemnt soon, coolant is below min line, Suspension noise when turning into an incline.