



805 SW 10th St.
Renton, WA 98057
(425) 217-2277
www.ecoautonw.com

Customer: 10320 **Stock #:** **VIN: 5YJYGDEE3MF082789** **2021 Tesla Model Y AWD**

Op	Acct	Status	Op Code	
----	------	--------	---------	--

A	SCP	Complete	DIAG	Customer Pay
---	-----	----------	------	---------------------

- CUSTOMER STATES DIAGNOSIS
- DIAGNOSED AND FOUND LH CONTROL ARM TO BE SQUEAKING.

Labor	Tech	Hours	Sale
	1005	0.00	0.00

Totals: 0.00

B	SCP	Complete	CARM	Customer Pay
---	-----	----------	------	---------------------

- CUSTOMER STATES CONTROL ARMS SQUEAKING
- REPLACED CONTROL ARMS, SQUEAK IS NOW GONE. RECOMMEND REPLACING LOWER LATERAL AND COMPLIANCE LINKS SOON AS THEY ARE TORN AND WILL CAUSE NOISE IN THE NEAR FUTURE.

Labor	Tech	Hours	Sale
	1005	1.00	210.00

Parts	QTY	Part #	Description	Price	Core Chg	Core Crd	Sale
	1	DA-K818855	RH SIDE UPPER CONTROL ARM	116.83	0.00	0.00	116.83
	1	DA-K818856		116.83	0.00	0.00	116.83

Totals: Labor: 210.00 Parts: 233.66 443.66

Other	Description	
-------	-------------	--

	State Sales Tax & City Sales Ta	46.58
	Shop Supplies & Technology F	10.00
	CC Surcharge Fee	15.01

Labor: 210.00 Parts: 233.66 Sublet: 0.00 Taxes: 46.58 Charges: 25.01 Discounts: 0.00 Total: 515.25

Customer Pay Total 515.25

Payments	Payment Date	
Visa	04/06/2026	-500.24
Visa	04/06/2026	-15.01

Amount Due 0.00

RO Total 515.25

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	233.66				233.66
Labor	210.00				210.00
Deductible	0.00	0.00	0.00		
Taxes	46.58	0.00	0.00	0.00	46.58
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	25.01	0.00	0.00	0.00	25.01
Payer Total	515.25	0.00	0.00		515.25