



805 SW 10th St.
Renton, WA 98057
(425) 217-2277
www.ecoautonw.com

Customer: 10209 Stock #: VIN: 5YJSA1E11FF114760 2015 Tesla Model S RWD

Op	Acct	Status	Op Code	
A	SCP		COMP	Customer Pay

- A/C COMPRESSOR

- TECHNICIAN FOUND THE AC COMPRESSOR AS WELL AS CHILLER, EVAPORATOR, HIGH DISCHARGE PRESSURE SENSOR, AND AMBIENT TEMP SENSOR ARE ALL FAULTING. RECOMENDING TO START WITH THE COMPRESSOR AS IT IS CONNECTED TO THE HV SYSTEM

Labor	Tech	Hours	Sale				
	1005	1.00	105.00				
Parts	QTY	Part #	Description	Price	Core Chg	Core Crd	Sale
	1	NPN-1028398-00-J	COMPRESSOR, A/C ELECTRIC - HVCC	1638.00	0.00	0.00	1638.00
Totals:	Labor: 105.00		Parts: 1638.00				1743.00

B	SCP	Deferred	MISC	**DEFERRED**
---	-----	----------	------	---------------------

- CHILLER

Labor	Tech	Hours	Sale
	1005	0.40	84.00
Totals:	Labor: 84.00		84.00

C	SCP		MISC	Customer Pay
---	-----	--	------	---------------------

- DRIVERS SIDE LOUVER

Labor	Tech	Hours	Sale				
	1005	0.80	168.00				
Parts	QTY	Part #	Description	Price	Core Chg	Core Crd	Sale
	1	NPN-1007268-00-F	DRIVERS SIDE LOUVER	171.50	0.00	0.00	171.50
Totals:	Labor: 168.00		Parts: 171.50				339.50

Other	Description	
	State Sales Tax & City Sales Ta	218.66
	Shop Supplies & Technology F	10.00

Labor: 273.00 Parts: 1809.50 Sublet: 0.00 Taxes: 218.66 Charges: 10.00 Discounts: 0.00 Total: 2311.16

Customer Pay Total 2311.16

RO Total 2311.16

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	1809.50				1809.50
Labor	357.00				357.00
Deductible	0.00	0.00	0.00		
Taxes	218.66	0.00	0.00	0.00	218.66
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	10.00	0.00	0.00	0.00	10.00
Payer Total	2311.16	0.00	0.00		2311.16