



805 SW 10th St.
 Renton, WA 98057
 (425) 217-2277
 www.ecoautonw.com

Customer: 10254 Stock #: VIN: 5YJSA1E28FF115655 2015 Tesla Model S AWD

Op	Acct	Status	Op Code	
A	SCP	Posted	MISC	Customer Pay

- SEAT TRACK NOT MOVING

- TECHNICIAN WAS ABLE TO FIND THE ROOT CAUSE OF THIS ISSE. AFTER INSPECTING THE SEAT, TECHNICIAN FOUND THE SEAT TRACK MOTOR ARM TO HAVE FALLED OUT OF THE MOTOR. AFTER MANUALLY MOVING THE SEAT, THE ARM WAS REINSTALLED.

Labor	Tech	Hours	Sale
	1005	0.50	105.00
Totals:	Labor: 105.00		105.00

Other	Description	
	State Sales Tax & City Sales Ta	11.03
	Shop Supplies & Technology F	10.00
	CC Surcharge Fee	3.78

Labor: 105.00	Parts: 0.00	Sublet: 0.00	Taxes: 11.03	Charges: 13.78	Discounts: 0.00	Total:	129.81
----------------------	--------------------	---------------------	---------------------	-----------------------	------------------------	---------------	---------------

Customer Pay Total 129.81

Payments	Payment Date	
Visa	02/25/2026	-126.03
Visa	02/25/2026	-3.78
	Amount Due	0.00

RO Total 129.81

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	0.00				0.00
Labor	105.00				105.00
Deductible	0.00	0.00	0.00		
Taxes	11.03	0.00	0.00	0.00	11.03
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	13.78	0.00	0.00	0.00	13.78
Payer Total	129.81	0.00	0.00		129.81