



805 SW 10th St.  
Renton, WA 98057  
(425) 217-2277  
www.ecoautonw.com

Customer: 10209 Stock #: VIN: 5YJSA1E11FF114760 2015 Tesla Model S RWD

Op	Acct	Status	Op Code					
A	SCP		COMP				<b>Customer Pay</b>	
-	A/C COMPRESSOR							
-	TECHNICIAN FOUND THE AC COMPRESSOR AS WELL AS CHILLER, EVAPORATOR, HIGH DISCHARGE PRESSURE SENSOR, AND AMBIENT TEMP SENSOR ARE ALL FAULTING. RECOMENDING TO START WITH THE COMPRESSOR AS IT IS CONNECTED TO THE HV SYSTEM							
	<i>Labor</i>	<i>Tech</i>			<i>Hours</i>		<i>Sale</i>	
		1005			1.00		105.00	
	<b>Totals:</b>	Labor: 105.00						105.00
B	SCP		MISC				<b>Customer Pay</b>	
-	CHILLER							
	<i>Labor</i>	<i>Tech</i>			<i>Hours</i>		<i>Sale</i>	
		1005			0.40		84.00	
	<b>Totals:</b>	Labor: 84.00						84.00
C	SCP		MISC				<b>Customer Pay</b>	
-	DRIVERS SIDE LOUVER							
	<i>Labor</i>	<i>Tech</i>			<i>Hours</i>		<i>Sale</i>	
		1005			0.80		168.00	
	<b>Totals:</b>	Labor: 168.00						168.00
D	SCP		MISC				<b>Customer Pay</b>	
-	FR DOOR HANDEL REPLACE							
	<i>Labor</i>	<i>Tech</i>			<i>Hours</i>		<i>Sale</i>	
		1005			0.90		189.00	
	<b>Totals:</b>	Labor: 189.00						189.00

Other						Description	
						State Sales Tax & City Sales Ta	57.33
						Shop Supplies & Technology F	10.00
<b>Labor:</b>	546.00	<b>Parts:</b>	0.00	<b>Sublet:</b>	0.00	<b>Taxes:</b>	57.33
		<b>Charges:</b>	10.00	<b>Discounts:</b>	0.00	<b>Total:</b>	<b>613.33</b>

**Customer Pay Total 613.33**  
**RO Total 613.33**

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	0.00				0.00
Labor	546.00				546.00
Deductible	0.00	0.00	0.00		
Taxes	57.33	0.00	0.00	0.00	57.33
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	10.00	0.00	0.00	0.00	10.00
<b>Payer Total</b>	<b>613.33</b>	<b>0.00</b>	<b>0.00</b>		<b>613.33</b>