



805 SW 10th St.
 Renton, WA 98057
 (425) 217-2277
 www.ecoautonw.com

Customer: 10298 **Stock #:** **VIN:**

Op	Acct	Status	Op Code	
A	SCP		HVBT	Customer Pay

- CUSTOMER STATES HV BATTERY HAS WATER INGRESS

- CUSTOMER STATES HV BATTERY HAS WATER INGRESS, FURTHER DIAGNOSIS IS NEEDED. HIGH VOLTAGE BATTERY REPAIR WILL BE DEEMED AFTER ASSESSING THE STATE OF THE MODULES IN THE BATTERY PACK. AFTER LOOKING AT VEHICLE LOGS, THE CAR HAS SOME HVIL AND ISOLATION ALERTS NOT ALLOWING THE VEHICLE TO DRIVE. ON SITE DIAG IS NEEDED. FOR A HV BATTERY REPAIR WE WILL NEED ABOUT 18 HOURS TO OPEN THE BATTERY, ASSESS THE DAMAGE, AND RECOVER/REPAIR ITEMS AS NEEDED. THIS ESTIMATE INCLUDES LABOR AND ANY PARTS NEEDED AFTER ASSESSING THE ISSUE.

Labor	Tech	Hours	Sale
	1005	18.00	8500.00
Totals:	Labor: 8500.00		8500.00

Other	Description	
	State Sales Tax & City Sales Ta	892.50
	Shop Supplies & Technology F	10.00

Labor: 8500.00 **Parts:** 0.00 **Sublet:** 0.00 **Taxes:** 892.50 **Charges:** 10.00 **Discounts:** 0.00 **Total:** **9402.50**

Customer Pay Total **9402.50**

RO Total **9402.50**

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	0.00				0.00
Labor	8500.00				8500.00
Deductible	0.00	0.00	0.00		
Taxes	892.50	0.00	0.00	0.00	892.50
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	10.00	0.00	0.00	0.00	10.00
Payer Total	9402.50	0.00	0.00		9402.50