



805 SW 10th St.
Renton, WA 98057
(425) 217-2277
www.ecoautonw.com

Customer: 10268 **Stock #:** **VIN:**

Op	Acct	Status	Op Code	
A	SCP	Complete	SUS	Customer Pay

- CUSTOMER STATES REBUILD SUSPENSION
- Rebuilt strut, installed. air suspension working properly.

Labor	Tech	Hours	Sale				
	1005	2.00	420.00				
Parts	QTY	Part #	Description	Price	Core Chg	Core Crd	Sale
	1	NPN F AIR SPRING RE	MX/MS REBUILD KIT	730.28	0.00	0.00	730.28
Totals:	Labor: 420.00		Parts: 730.28				1150.28

B	SCP	Complete	MISC	Customer Pay
---	-----	----------	------	---------------------

- Park Assist Check
- Seems to be an issue with the wiring harness further down the line. Tech suggest maybe wiring harness is clipped or damaged. Could also be related to the computer system. Unable to repair.

Labor	Tech	Hours	Sale
	1005	0.00	0.00
Totals:			0.00

C	SCP	Complete	MISC	Customer Pay
---	-----	----------	------	---------------------

- INSTALL WELCOME PLATES

Labor	Tech	Hours	Sale				
	1005	0.00	0.00				
Parts	QTY	Part #	Description	Price	Core Chg	Core Crd	Sale
	1	NPN-1053195-00-E	RH 2ND ROW WELCOME PLATE	78.00	0.00	0.00	78.00
	1	NPN-1053189-00-F	2ND ROW LH WELCOME PLATE	78.00	0.00	0.00	78.00
Totals:			Parts: 156.00				156.00

Other	Description	
	State Sales Tax & City Sales Ta	137.16
	Shop Supplies & Technology F	10.00

Labor: 420.00 Parts: 886.28 Sublet: 0.00 Taxes: 137.16 Charges: 10.00 Discounts: 0.00 Total: 1453.44

Customer Pay Total 1453.44

RO Total 1453.44

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	886.28				886.28
Labor	420.00				420.00
Deductible	0.00	0.00	0.00		
Taxes	137.16	0.00	0.00	0.00	137.16
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	10.00	0.00	0.00	0.00	10.00
Payer Total	1453.44	0.00	0.00		1453.44