



805 SW 10th St.  
 Renton, WA 98057  
 (425) 217-2277  
 www.ecoautonw.com

**Customer: 10195**      **Stock #:**      **VIN: 5YJXCAE27LF261976**      **2020 Tesla Model X AWD**

Op	Acct	Status	Op Code	
A	SCP	Posted	DIAG	<b>Customer Pay</b>

- CUSTOMER STATES SUSPENSTION IS MAKING NOISE ON SURFACE ROADS
- Tightened bolt in the front suspension that was causing the noise issue.

Labor	Tech	Hours	Sale
	1005	0.50	105.00
<b>Totals:</b>	Labor: 105.00		105.00

Other	Description	
	State Sales Tax & City Sales Ta	11.03
	Shop Supplies & Technology F	10.00
	CC Surcharge Fee	3.78

<b>Labor:</b> 105.00	<b>Parts:</b> 0.00	<b>Sublet:</b> 0.00	<b>Taxes:</b> 11.03	<b>Charges:</b> 13.78	<b>Discounts:</b> 0.00	<b>Total:</b>	<b>129.81</b>
----------------------	--------------------	---------------------	---------------------	-----------------------	------------------------	---------------	---------------

**Customer Pay Total 129.81**

Payments	Payment Date	
Visa	01/19/2026	-126.03
Visa	01/19/2026	-3.78

Amount Due 0.00

**RO Total 129.81**

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				<b>0.00</b>
Parts	0.00				<b>0.00</b>
Labor	105.00				<b>105.00</b>
Deductible	0.00	0.00	0.00		
Taxes	11.03	0.00	0.00	0.00	<b>11.03</b>
Discounts	0.00	0.00	0.00	0.00	<b>0.00</b>
Charges	13.78	0.00	0.00	0.00	<b>13.78</b>
<b>Payer Total</b>	<b>129.81</b>	<b>0.00</b>	<b>0.00</b>		<b>129.81</b>