



805 SW 10th St.  
 Renton, WA 98057  
 (425) 217-2277  
 www.ecoautonw.com

**Customer: 10254      Stock #:      VIN: 5YJSA1E28FF115655      2015 Tesla Model S AWD**

Op	Acct	Status	Op Code	
----	------	--------	---------	--

A	SCP	Complete	MISC	<b>Customer Pay</b>
---	-----	----------	------	---------------------

- SEAT TRACK NOT MOVING

- TECHNICIAN WAS ABLE TO FIND THE ROOT CAUSE OF THIS ISSE. AFTER INSPECTING THE SEAT, TECHNICIAN FOUND THE SEAT TRACK MOTOR ARM TO HAVE FALLED OUT OF THE MOTOR. AFTER MANUALLY MOVING THE SEAT, THE ARM WAS REINSTALLED.

Labor	Tech	Hours	Sale
	1005	0.50	105.00
<b>Totals:</b>	Labor: 105.00		105.00

Other	Description	
	State Sales Tax & City Sales Ta	11.03
	Shop Supplies & Technoloqy F	10.00

**Labor: 105.00    Parts: 0.00    Sublet: 0.00    Taxes: 11.03    Charges: 10.00    Discounts: 0.00    Total: 126.03**

**Customer Pay Total      126.03**

**RO Total      126.03**

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	0.00				0.00
Labor	105.00				105.00
Deductible	0.00	0.00	0.00		
Taxes	11.03	0.00	0.00	0.00	11.03
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	10.00	0.00	0.00	0.00	10.00
<b>Payer Total</b>	<b>126.03</b>	<b>0.00</b>	<b>0.00</b>		<b>126.03</b>