



805 SW 10th St.  
 Renton, WA 98057  
 (425) 217-2277  
 www.ecoautonw.com

**Customer: 10277**      **Stock #:**      **VIN:**

Op	Acct	Status	Op Code	
A	SCP	Posted	TPMS	<b>Customer Pay</b>
- CUSTOMER STATES TIRE PRESSURE LIGHT IS ON CHECK				
- read the code been faulting for a week. Replaced all 4 TPMS sensors.				

Labor	Tech	Hours	Sale				
	1005	1.00	210.00				
Parts	QTY	Part #	Description	Price	Core Chg	Core Crd	Sale
	4	TSLA - 1490701-01-E	TPMS SENSOR BLK BLUTH	78.00	0.00	0.00	312.00
<b>Totals:</b>	Labor: 210.00		Parts: 312.00				522.00

Other	Description	
	State Sales Tax & City Sales Ta	54.81
	Shop Supplies & Technology F	10.00

**Labor: 210.00    Parts: 312.00    Sublet: 0.00    Taxes: 54.81    Charges: 10.00    Discounts: 0.00    Total: 586.81**

**Customer Pay Total 586.81**

Payments	Payment Date	
Visa	03/11/2026	-586.81
	Amount Due	0.00

**RO Total 586.81**

Payer	Customer	Warranty	Extended Warranty	Internal	Total
Sublet	0.00				0.00
Parts	312.00				312.00
Labor	210.00				210.00
Deductible	0.00	0.00	0.00		
Taxes	54.81	0.00	0.00	0.00	54.81
Discounts	0.00	0.00	0.00	0.00	0.00
Charges	10.00	0.00	0.00	0.00	10.00
<b>Payer Total</b>	<b>586.81</b>	<b>0.00</b>	<b>0.00</b>		<b>586.81</b>